# Electromagnetic and Electromechanical Engineering Principles Notes 02 Magnetics and Energy Conversion

Marc T. Thompson, Ph.D. Thompson Consulting, Inc. 9 Jacob Gates Road Harvard, MA 01451 Phone: (978) 456-7722 Email: marctt@thompsonrd.com Website: http://www.thompsonrd.com

© Marc Thompson, 2006-2008 Portions of these notes reprinted from *<u>Fitzgerald</u>*, Electric Motors, 6<sup>th</sup> edition

#### Course Overview ---- Day 2

2	Magnetics and energy conversion		
	<ul> <li>Review of Maxwell's equations; demo; concepts of magnetic fields; Ampere's, Faraday's and Gauss' magnetic laws; Lorentz force law; magnetic circuits.</li> </ul>	7:30-9:30	1-54
	- Morning break	9:30-9:45	
	<ul> <li>Soft magnetic materials (steel); hysteresis and core losses</li> <li>Hard magnetic (permanent magnets) and PM circuits</li> </ul>	9:45-10:45 10:45-12:00	55-76 77-139
	- Lunch	12:00-1:00	
	<ul> <li>Comments on superconductors; basic transformers: analysis, equivalent circuits.</li> </ul>	1:00-2:45	140-208
	- Afternoon break	2:45-3:00	
	<ul> <li>Per-unit system.</li> <li>Begin electromechanical conversion; begin forces and torques</li> <li>Summarize.</li> </ul>	3:00-3:15 3:15-4:00 4:00	209-216 217-240 241

### **Overview of Magnetics**

- Review of Maxwell's equations
- Ampere's law, Gauss' law, Faraday's law
- Magnetic circuits
- Flux, flux linkage, inductance and energy

#### **Review of Maxwell's Equations**

- First published by James Clerk Maxwell in 1864
- Maxwell's equations couple electric fields to magnetic fields, and describe:
  - Magnetic fields
  - Electric fields
  - Wave propagation (through the wave equation)
- There are 4 Maxwell's equations, but in magnetics we generally only need 3:
  - Ampere's Law
  - Faraday's Law
  - Gauss' Magnetic Law



James Clerk Maxwell

#### Review of Maxwell's Equations

• We'll review Maxwell's equations in words, followed by a little bit of mathematics and some computer simulations showing the magnetic fields

### Ampere's Law

• Flowing current creates a magnetic field

$$\oint_C \vec{H} \cdot d\vec{l} = \int_S \vec{J} \cdot d\vec{A} + \frac{d}{dt} \int_S \varepsilon_o \vec{E} \cdot d\vec{A}$$

 In magnetic systems, generally there is high current and low voltage (and hence low electric field) and we can approximate for low *d/dt*.

$$\oint_C \vec{H} \cdot d\vec{l} \approx \int_S \vec{J} \cdot d\vec{A}$$

 In words: the magnetic flux density integrated around <u>any</u> closed contour equals the net current flowing through the surface bounded by the contour Electromechanics





André-Marie Ampère

### Finite-Element Analysis (FEA)

- Very useful tool for visualizing and solving shapes and magnitudes of magnetic fields
- FEA is often used to simulate and predict the performance of motors, etc.
- Following we'll see some 2-dimensional (2D) FEA results to help explain Maxwell's equations

# Field From Current Loop, NI = 500 A-turns

• Coil radius R = 1"; plot from 2D finite-element analysis



# Faraday's Law

• A changing magnetic flux impinging on a conductor creates an electric field and hence a current (eddy current)

$$\oint_C \vec{E} \cdot d\vec{l} = -\frac{d}{dt} \int_S \vec{B} \cdot d\vec{A}$$

- The electric field integrated around a closed contour equals the net time-varying magnetic flux density flowing through the surface bound by the contour
- In a conductor, this electric field creates a current by:  $\vec{J} = \sigma \vec{E}$





**Michael Faraday** 

Induction motors, brakes, etc.

Electromechanics

Circular Coil Above Conducting Aluminum Plate

- Flux density plots at DC and 60 Hz
- At 60 Hz, currents induced in plate via magnetic induction create lift force

<u>DC</u>



<u>60 Hz</u>



# Demonstration of Faraday's Law: Electrodynamic Drag (NdFeB Magnet-in-Tube)

- Process:
  - Moving magnet creates changing magnetic field in copper tube
  - Changing magnetic field creates induced voltage
  - Induced voltage creates current
  - By Lorentz force law, induced current and applied magnetic field create drag force

# Gauss' Magnetic Law

• Gauss' magnetic law says that the integral of the magnetic flux density over any closed surface is zero, or:

$$\oint_{S} B \cdot dA = 0$$

- This law implies that magnetic fields are due to electric currents and that magnetic charges ("monopoles") do not exist.
- Note: similar form to KCL in circuits. (We'll use this analogy later...)



**Carl Friedrich Gauss** 

# Gauss' Law --- Continuity of Flux Lines



Figure 3-13 Continuity of flux.

$$\phi_1 + \phi_2 + \phi_3 = 0$$

Reference: N. Mohan, et. al., Power Electronics Converters, Applications and Design, Wiley, 2003, pp. 48

Electromechanics

#### Lorentz Force Law

• Experimentally derived rule:

$$F = \int J \times B dV$$

• For a wire of length / carrying current / perpendicular to a magnetic flux density *B*, this reduces to:

$$F = IBl$$

# Lorentz Force Law and the Right Hand Rule $F = \int J \times B dV$



Reference: http://www.physics.brocku.ca/faculty/sternin/120/slides/rh-rule.htmlElectromechanicsMagnetics and Energy Conversion

### Intuitive Thinking about Magnetics

- By Ampere's Law, the current **J** and the magnetic field **H** are generally at right angles to one another
- By Gauss' law, magnetic field lines loop around on themselves
  - No magnetic monopole
- You can think of high-  $\mu$  magnetic materials such as steel as an easy conduit for magnetic flux.... i.e. the flux easily flows thru the high-  $\mu$  material

# Magnetic Field (H) and Magnetic Flux Density (B)

- *H* is the magnetic field (A/m in SI units) and *B* is the magnetic flux density (Weber/m<sup>2</sup>, or Tesla, in SI units)
- **B** and **H** are related by the magnetic permeability  $\mu$  by **B** =  $\mu$ **H**
- Magnetic permeability  $\mu$  has units of Henry/meter
- You can think of high-  $\mu$  magnetic materials such as steel as an easy conduit for magnetic flux.... i.e. the flux easily flows thru the high-  $\mu$  material
- In free space  $\mu_o = 4\pi \times 10^{-7}$  H/m
- Note that **B** and **H** are vectors; they have both a magnitude and a direction

#### Right Hand Rule and Direction of Magnetic Field

B-field curves



Reference: http://sol.sci.uop.edu/~jfalward/magneticforcesfields/magneticforcesfields.htmlElectromechanicsMagnetics and Energy Conversion

#### Forces Between Current Loops



Reference: http://sol.sci.uop.edu/~jfalward/magneticforcesfields/magneticforcesfields.html

Electromechanics

# Inductor Without Airgap

• Magnetic flux is constrained to flow within steel



#### Constitutive relationships

In free space:

 $B = \mu_o H$ 

Magnetic permeability of free space  $\mu_0 = 4\pi \times 10^{-7}$  Henry/meter. In magnetic material, magnetic permeability is higher than  $\mu_0$ :  $B = \mu H$ 



$$\frac{B_c}{\mu_c}l_c + \frac{B_g}{\mu_o}g = NI$$

Electromechanics



#### Magnetic Circuits

• Use Ohm's law analogy to model magnetic circuits

 $V \Leftrightarrow NI$  $I \Leftrightarrow \Phi$  $R \Leftrightarrow \Re$ 

• Use magnetic "reluctance" instead of resistance

$$R = \frac{l}{\sigma A} \Leftrightarrow \Re = \frac{l}{\mu A}$$

• This is a <u>very</u> powerful method to get approximate answers in magnetic circuits

#### Magnetic-Electric Circuit Analogy

- In an electric circuit, voltage V forces current I to flow through resistances R
- In a magnetic circuit, MMF NI forces flux  $\Phi$  to flow through reluctances  $\Re$



# C-Core with Gap --- Using Magnetic Circuits

• Flux in the core is easily found by:

$$\Phi = \frac{NI}{\Re_{core} + \Re_{gap}} = \frac{NI}{\frac{l_p}{\mu_c A_c} + \frac{g}{\mu_o A_c}}$$

• Now, note what happens if  $g/\mu_o >> I_p/\mu_c$ : The flux in the core is now approximately independent of the core permeability, as:



- Electromechanics

Magnetics and Energy Conversion





#### Example: C-Core with Airgap

 <u>Fitzgerald</u>, Example 1.1; with B<sub>c</sub> = 1.0T, find reluctances, flux and coil current



$$\Re_{c} = \frac{l_{c}}{A_{c}\mu_{c}} = \frac{0.3}{(70,000)(4\pi \times 10^{-7})(9 \times 10^{-4})} = 3.8 \times 10^{3} \frac{A - turns}{Wb}$$
  
$$\sigma = 5 \times 10^{-4} \qquad c A = turns$$

$$\Re_{g} = \frac{g}{A_{g}\mu_{o}} = \frac{5 \times 10^{-7}}{(4\pi \times 10^{-7})(9 \times 10^{-4})} = 4.4 \times 10^{5} \frac{A - turns}{Wb}$$

Note that  $\mathbb{R}_{g} >> \mathbb{R}_{c}$ 

Electromechanics

#### Example: C-Core with Airgap



Flux:

$$\Phi = B_c A_c = (1.0)(9 \times 10^{-4}) = 9 \times 10^{-4} Wb$$

Coil current:

$$M = \Phi(\Re_c + \Re_g)$$
$$\Rightarrow I = \frac{\Phi(\Re_c + \Re_g)}{N} = \frac{(9 \times 10^4)(4.46 \times 10^5)}{500} = 0.8 A$$

Electromechanics

#### Example: C-Core with Airgap --- FEA

• NI = 400 A-turns



#### Example: C-Core with Airgap --- FEA

#### • NI = 400 A-turns, close up near the core



# Example: C-Core with Airgap --- FEA Result

• Flux density in the core is approximately 1 Tesla





#### Example: C-Core with Airgap --- Gap Detail



# Example: Simple Synchronous Machine

- *Fitzgerald*, Example 1.2
- Assuming  $\mu \rightarrow \infty$ , find airgap flux  $\Phi$  and flux density B<sub>g</sub> Assume I = 10A, N = 1000 turns, g = 1 cm and A<sub>g</sub> = 2000 cm<sup>2</sup>



#### Aside: What Does Infinite Core µ Imply?



In core,  $B_c$  is finite; this means that if  $\mu \rightarrow \infty$ , then  $H_c \rightarrow 0$  for finite  $B_{c.}$  Also, infinite  $\mu$  implies zero reluctance

# Example: Simple Synchronous Machine

- Some initial thoughts, before doing any equations:
  - By symmetry, airgap flux and flux density are the same in both gaps
  - Since permeability is infinite, H inside steel is zero




# Flux Linkage, Voltage and Inductance

• By Faraday's law, changing magnetic flux density creates an electric field (and a voltage)

$$\oint_C \vec{E} \cdot d\vec{l} = -\frac{d}{dt} \int_S \vec{B} \cdot d\vec{A}$$

• Induced voltage:

$$v = N \frac{d\Phi}{dt} = \frac{d\lambda}{dt}$$

$$\lambda = "flux linkage" = N\Phi$$

Inductance relates flux linkage to current



Electromechanics



# Finding Inductance Using Magnetic Circuits

- Let's at first assume infinite core permeability; this means that the reluctance of the core is zero
- Note that inductance always scales as N<sup>2</sup> (why is that?)



Electromechanics



Reluctances: 
$$\Re_1 = \frac{g_1}{\mu_o A_1}$$
 and  $\Re_2 = \frac{g_2}{\mu_o A_2}$ 

Inductance:

$$L = \frac{\lambda}{I} = \frac{N\Phi}{I} = N^2 \left(\frac{\Re_1 + \Re_2}{\Re_1 \Re_2}\right) = \mu_o N^2 \left(\frac{A_1}{g_1} + \frac{A_2}{g_2}\right)$$

Electromechanics

# Magnetic Circuit with Two Airgaps (cont.)



Flux in leg#2: 
$$\Phi_2 = \frac{NI}{\Re_2} = \frac{\mu_o A_2 NI}{g_2}$$

Flux density in leg#1: 
$$B_1 = \frac{\Phi_1}{A_1} = \frac{\mu_o NI}{g_1}$$
  
Flux density in leg#2:  $B_2 = \frac{\Phi_2}{A_2} = \frac{\mu_o NI}{g_2}$ 

Magnetics and Energy Conversion

Electromechanics

# Inductance vs. Relative Permeability

- What happens if we assume <u>finite</u> core permeability?
- Reluctance of the core is now finite as well



#### Inductance vs. Relative Permeability



#### Example: Effects of Finite Permeability <u>Fitzgerald</u>, problem 1.5

Cross-sectional area  $A_c = 1.8 \times 10^{-3} \text{ m}^2$ Mean core length  $l_c = 0.6 \text{ m}$ Gap length  $g = 2.3 \times 10^{-3} \text{ m}$ N = 83 turns



1.5 The magnetic circuit of Problem 1.1 has a nonlinear core material whose permeability as a function of  $B_{\rm m}$  is given by

$$\mu = \mu_0 \left( 1 + \frac{3499}{\sqrt{1 + 0.047(B_{\rm m})^{7.8}}} \right)$$

where  $B_{\rm m}$  is the material flux density.

- a. Using MATLAB, plot a dc magnetization curve for this material ( $B_{\rm m}$  vs.  $H_{\rm m}$ ) over the range  $0 \le B_{\rm m} \le 2.2$  T.
- b. Find the current required to achieve a flux density of 2.2 T in the core.
- c. Again, using MATLAB, plot the coil flux linkages as a function of coil current as the current is varied from 0 to the value found in part (b).

• Relative  $\mu$  vs. B



Electromechanics

• B/H curve



Magnetics and Energy Conversion

#### Current calculation

Cross-sectional area  $A_c = 1.8 \times 10^{-3} \text{ m}^2$ Mean core length  $l_c = 0.6 \text{ m}$ Gap length  $g = 2.3 \times 10^{-3} \text{ m}$ N = 83 turns



From Ampere's law:

$$H_c l_c + H_g g = NI$$

In core:  $H_c = \frac{B_c}{\mu}$ 

In gap (let's assume  $B_c = B_g = B$ ):  $H_g = \frac{B}{\mu_o}$ 

Put this back into Ampere's law:

$$\frac{Bl_c}{\mu} + \frac{Bg}{\mu_o} = NI$$
  
$$\therefore I = \left(\frac{B}{\mu_o N}\right) \left(\frac{l_c}{\mu_r} + g\right) = 65.8A$$

- Coil flux linkage  $\lambda$  as a function of coil current
- Note that at low current,  $\lambda$ -I curve is linear, indicating constant inductance



Magnetics and Energy Conversion

```
Example:
MATLAB Script
```

```
% Fitzgerald, problem 1.5
 % Constants
 munot=4*pi*1e-7;
  Part a
 ມທ໌=0:0.01:2.2;
 mu=munot*(1+3499./(sqrt(1+0.047*Bm.^7.8)))
 plot(Bm,mu/munot,'k')
 xlabel('Bm, Tesla')
 ylabel('Relative mu')
 grid
 title('Relative mu vs. B, problem 1.5')
 mu_rel=mu(length(mu))/munot
 figure
 Hm=Bm./mu;
 plot(Hm,Bm,'k')
 xlabel('H [A/m]')
 vlabel('B [T]')
 grid;
 title('Bm vs. Hm, problem 1.5')
 % Part b
 B=2.2;
N = 83;
 lc=0.6;
g=2.3e-3;
I=(B/(munot*N))*(lc/mu rel + g)
 % part c
Ac=1.8e-3;
 figure
J_{=}(Bm/(munot*N)).*(lc./(mu/munot)+g);
  lux linkage=N*Bm*Ac;
>plot(I,flux linkage);
xlabel('I [A]')
ylabel('Flux linkage [Wb]')
 title('Coil flux linkage as a function of I, problem 1.5')
grid
```

### Inductance and Energy

• Magnetic stored energy (in Joules) is:

$$W = \frac{1}{2}LI^2$$

• This is a good thing to remember

• Note that flux is the sum of flux due to  $i_1$  and that due to  $i_2$ 



 Note that by the right-hand rule the flux due to i<sub>1</sub> and i<sub>2</sub> are additive given the current directions shown



 Note that by the right-hand rule the flux due to i<sub>1</sub> and i<sub>2</sub> are additive given the current directions shown



Flux: 
$$\Phi = (N_1 i_1 + N_2 i_2) \left( \frac{\mu_o A_c}{g} \right)$$

Flux linkage for coil #1:

$$\lambda_1 = N_1 \Phi = N_1^2 i_1 \left(\frac{\mu_o A_c}{g}\right) + N_1 N_2 i_2 \left(\frac{\mu_o A_c}{g}\right)$$

We can write this as:

$$\lambda_1 = L_{11}i_1 + L_{12}i_2$$

 $L_{11}$  is "self inductance" of coil #1  $L_{12}$  is "mutual inductance" between coils #1 and #2

Eline linkaga far agil 40.



$$\lambda_2 = N_2 \Phi = N_1 N_2 i_1 \left(\frac{\mu_o A_c}{g}\right) + N_2^2 i_2 \left(\frac{\mu_o A_c}{g}\right)$$

Or rewriting:  $\lambda_2 = L_{21}i_1 + L_{22}i_2$ 

Or, in matrix form:  $\begin{bmatrix} \lambda_1 \\ \lambda_2 \end{bmatrix} = \begin{bmatrix} L_{11} & L_{12} \\ L_{21} & L_{22} \end{bmatrix} \begin{bmatrix} i_1 \\ i_2 \end{bmatrix}$ 

# "Soft" Magnetic Materials

- Materials with a small B/H curve, such as steels, etc.
- Much of the previous analysis assumed that steel had infinite permeability (µ → ∞) or that permeability was constant and large.
- However, soft magnetic materials exhibit both saturation and losses

# **B-H Curve and Saturation**

• Definition of magnetic permeability: slope of B-H curve



Figure 3-12 Relation between *B*- and *H*-fields.

Reference: N. Mohan, et. al., *Power Electronics Converters, Applications and Design*, Wiley, 2003, pp. 48

# BH Curve for M-5 Steel

#### • Note horizontal scale is logarithmic



Electromechanics

#### Hysteresis Loop

- Real-world magnetic materials have a "hysteresis loop"
- Hysteresis loss is proportional to shaded area



# B-H Loop for M-5 Grain-Oriented Steel

• Only the top half of the loops shown for steel 0.012" thick



Magnetics and Energy Conversion

#### **BH Curves for Various Soft Magnetic Materials**



**FIGURE 1.27** The *B*-*H* curves of various soft magnetic materials.

Reference: E. Furlani, *Permanent Magnet and Electromechanical Devices*, Academic Press, 2001, pp. 41

Electromechanics

#### Relationship Between Voltage, Flux and Current



#### Exciting RMS VA per kg at 60 Hz



# Hysteresis Loop Size Increases with Frequency

• Hysteresis loss increases as frequency increases



Fig. 2.3 Hysteresis loops at different frequencies

Reference: Siemens, Soft Magnetic Materials (Vacuumschmelze Handbook), pp. 30

Electromechanics

# **Total Core Loss**

- Total core loss is the sum of:
  - Hysteresis loss
  - Eddy current losses
- Eddy current losses are due to induced currents (via Faraday's law)
- Eddy current losses are minimized by <u>laminating</u> magnetic cores

#### Laminated Core

 Cores made from conductive magnetic materials must be made of many thin laminations. Lamination thickness < skin depth.



#### Eddy Current Loss in Lamination



# **Total Core Loss**

#### • M-5 steel at 60 Hz



Total Core Loss vs. Frequency and B<sub>max</sub>

- Core loss depends on peak flux density and excitation frequency
- This is the curve for a high frequency core material



Reference: http://www.jfe-steel.co.jp/en/products/electrical/jnhf/02.html

Electromechanics

#### **Process to Find Core Loss**



# Example: C-Core with Airgap --- Current

• <u>*Fitzgerald*</u>, Example 1.7; find the current necessary to produce  $B_c = 1T$ 



$$A_{c} = A_{g} = 9 \text{ cm}^{2}$$
  
 $g = 0.05 \text{ cm}$   
 $l_{c} = 30 \text{ cm}$   
 $N = 500$   
 $\mu_{g} = 70,000$ 

Electromechanics

**Example: C-Core with Airgap --- Solution** The value of  $H_c$  needed for  $B_c = 1$  Tesla is read from the chart:

 $H_c = 11 A - turns / meter$ 

The MMF drop in the core is:  $H_c l_c = (11)(0.3) = 33 A - turns$ 

The MMF drop in the airgap is:  $H_g g = \frac{B_g g}{\mu_o} = \frac{(1.0)(5 \times 10^{-4})}{4\pi \times 10^{-7}} = 396 \text{ A} - turns$ 

The winding current is:

$$I = \frac{\sum MMF}{N} = \frac{33 + 396}{500} = 0.8A$$

## Example: Inductor

• *<u>Fitzgerald</u>*, Example 1.8



Figure 1.15 Laminated steel core with winding for Example 1.8.

Material: M-5 steel f = 60 HzN=200

 $B_c = 1.5 \sin \omega t$  Tesla Steel is 94% of cross section Density of steel = 7.65 g/cm<sup>3</sup>

Find:

(a) Applied voltage(b) Peak current(c) RMS current(d) Core loss
#### Example: Excitation Voltage From Faraday's law:

$$e = \frac{d\lambda}{dt} = N\frac{d\Phi}{dt} = NA_c \frac{dB_c}{dt}$$

 $A_c = 2in \times 2in \times 0.94 = 3.76in^2 = 2.4 \times 10^{-3} m^2$ 

$$\frac{dB_c}{dt} = (1.5\omega)\cos(\omega t) = 565\cos(\omega t)$$

$$e = (200)(2.4 \times 10^{-3})(565\cos(\omega t)) = 274\cos(\omega t)$$



Figure 1.10 . Do magnetization curve for M-5 grain-oriented electrical steel 0.012 in thick. (Armon Inc.)

From Figure 1.10, B = 1.5T requires H = 36 A-turns/m

From Ampere's law,  $Hl_c = NI$ 

$$I_c = 2 \times (8"+6") = 28" = 0.71$$
m

$$I = \frac{Hl_c}{N} = \frac{(36)(0.71)}{200} = 0.13A$$

Electromechanics

#### Example: RMS Winding Current



Figure 1.12 Exciting rms voltamperes per kilogram at 60 Hz for M-5 grain-oriented electrical steel 0.012 in thick. (Armco Inc.)

From Figure 1.12, at  $B_{max}$  = 1.5T,  $P_a$  = 1.5 VA/kg

Core volume:

 $V_c = (4in^2)(0.94)(28in) = 105.5 in^3 = 1.7 \times 10^{-3} m^3$ 

Core mass:

$$M = V_c \rho_c = (1.7 \times 10^{-3} m^3)(7650 \frac{kg}{m^3}) = 13.2 \ kg$$

Core Volt-  
Amperes: 
$$P_c = 1.5 \frac{VA}{kg} \times 13.2 \ kg = 19.8 \ VA$$

Current: 
$$I_{RMS} = \frac{VA}{E_{RMS}} = \frac{19.7}{\left(\frac{274}{\sqrt{2}}\right)} = 0.10A$$



Figure 1.14 Core loss at 60 Hz in watts per kilogram for M-5 grain-oriented electrical steel 0.012 in thick. (*Armco Inc.*)

From Figure 1.14, core loss density = 1.5 W/kg at B<sub>max</sub> = 1.5 Tesla. Total core loss is:

$$P_c = M \times 1.5 \frac{W}{kg} = (13.2)(1.5) = 20W$$

- "Soft" magnetic materials such as magnetic steel can behave as very weak permanent magnets
- Permanent magnets, or "hard" magnetic materials, have a high coercive force H<sub>c</sub> and can produce significant flux in an airgap; they also have a "wide" hysteresis loop



FIGURE 1.25 The *B*-*H* loops for soft and hard magnetic materials.

Reference: E. Furlani, Permanent Magnet and Electromechanical Devices, Academic Press, 2001, pp. 39ElectromechanicsMagnetics and Energy Conversion

## **Brief History of Permanent Magnets**

- c. 1000 BC: Chinese compasses using lodestone
  - Later used to cross the Gobi desert



Fig. 2 Man-shaped compass mounted on a chariot, after Kartsev [2]



Fig. 3 Chinese spoon compass

Reference: K. Overshott, "Magnetism: it is permanent," IEE Proceedings-A, vol. 138, no. 1, Jan. 1991, pp. 22-31

Electromechanics

#### **Brief History of Permanent Magnets**



Figure 1.1 Magnetic needles for compasses are being made by craftsmen in this print of 1637. Good steel was manufactured in China from 500 A.D. onwards.

Reference: R. Parker, Advances in Permanent Magnetism, John Wiley, 1990, pp. 3

- c. 200 BC: Lodestone (magnetite) known to the Greeks
   Touching iron needles to magnetite magnetized them
- 1200 AD: French troubadour de Provins describes use of a primitive compass to magnetize needles
- 1600: William Gilbert publishes first journal article on permanent magnets
- 1819: Oersted reports that an electric current moves compass needle

References:

1. K. Overshott, "Magnetism: it is permanent," IEE Proceedings-A, vol. 138, no. 1, Jan. 1991, pp. 22-31

2. R. Petrie, "Permanent Magnet Material from Loadstone to Rare Earth Cobalt," *Proc. 1995 Electronics Insulation and Electrical Manufacturing and Coil Winding Conf.*, pp. 63-64

3. Rollin Parker, Advances in Permanent Magnetism, John Wiley, 1990

4. E. Hoppe, "Geshichte des Physik," Vieweg, Braunshweig, 1926, pp. 339

5. W. Gilbert, "De Magnete 1600," translation by S. P. Thompson, 1900, republished by Basic Books, Inc., New York, 1958

- c. 1825: Sturgeon invents the electromagnet, resulting in a way to artificially magnetize materials
- 7-ounce magnet was able to lift 9 pounds



References:

1. W. Sturgeon, Mem. Manchester Lit. Phil. Soc., 1846, vol. 7, pp. 625

2. Britannica Online

Electromechanics

 c. 1830: Joseph Henry (U.S.) constructs electromagnets



**Joseph Henry** 



Photo reference: Smithsonian Institute archives

- 1917: Cobalt magnet steels developed by Honda and Takagi in Japan
- 1940: Alnico --- first "modern" material still in common use — Good for high temperatures
- 1960: SmCo (samarium cobalt) rare earth magnets
   Good thermal stability
- 1983: GE and Sumitomo develop neodymium iron boron (NdFeB) rare earth magnet
  - Highest energy product, but limited temperature range

References:

1. K. Overshott, "Magnetism: it is permanent," IEE Proceedings-A, vol. 138, no. 1, Jan. 1991, pp. 22-31

2. R. Petrie, "Permanent Magnet Material from Loadstone to Rare Earth Cobalt," *Proc. 1995 Electronics Insulation and Electrical Manufacturing and Coil Winding Conf.*, pp. 63-64

Electromechanics

# Magnetizing Permanent Magnets

- Material is placed inside magnetizing fixture
- Magnetizing coil is energized with a current producing sufficient field to magnetize the PM material









Reference: E. Furlani, *Permanent Magnet and Electromechanical Devices*, Academic Press, 2001, pp. 57

#### **Pictorial View of Magnetization Process**



Figure 3.6 Pictorial explanation of magnetization curve in a ferromagnetic bar.

 $\mathcal{F}$ 

Reference: R. Parker, Advances in Permanent Magnetism, John Wiley, 1990, pp. 49

Electromechanics

• External effects of permanent magnets can be modeled as surface current



Figure 1.4. Uniformly magnetized magnet (a), which may be modeled by a current density over its boundary (b).



Reference: P. Campbell, *Permanent Magnet Materials and their Applications*, Cambridge University Press, 1994, pp. 7

• After magnetization, **M** has values of either +Msat or -Msat



Figure 1.10. Intrinsic magnetization characteristic for an elemental volume of a magnet.

Reference: P. Campbell, Permanent Magnet Materials and their Applications, Cambridge University Press, 1994, pp. 14-15

Electromechanics

- By a constitutive relationship,  $\mathbf{B} = \mu_0(\mathbf{H} + \mathbf{M})$
- Since **M** has values of either +Msat or -Msat, it follows that the slope of the BH curve for the permanent magnet is  $\mu_o$





Figure 1.17. B versus H characteristic for a magnet with  $|H_{ci}| < M_{sat}$ .

Reference: P. Campbell, Permanent Magnet Materials and their Applications, Cambridge University Press, 1994, pp. 15, 23

Electromechanics

## **Demagnetization Curves of Ceramic 8**

• Typical sintered ceramic magnet



Figure 3.3. Demagnetization curves of Ceramic 8 at various temperatures.

Reference: P. Campbell, Permanent Magnet Materials and their Applications, Cambridge University Press, 1994, pp. 62

## Demagnetization Curves for NdFeB

• Strong neodymium-iron-boron



Figure 3.14. Demagnetization curves of (Nd, Dy)-Fe-B at various temperatures.

Reference: P. Campbell, <u>Permanent Magnet Materials and their Applications</u>, Cambridge University Press, 1994, pp. 74ElectromechanicsMagnetics and Energy Conversion

#### Permanent Magnets vs. Steel

• Note that PM has much higher coercive force



# Lines of Force Iron filings follow magnetic field lines



#### **Cast Alnico**



Figure 4.3 Typical cast Alnico magnet configurations.

Reference: R. Parker, Advances in Permanent Magnetism, John Wiley, 1990, pp. 65

Electromechanics

# Example: PM in Magnetic Circuits

• *Fitzgerald*, Example 1.9



g = 0.2 cm

$$I_{m} = 1.0 \text{ cm}$$

$$A_{\rm m} = A_{\rm g} = 4 \ \rm cm^2$$

Find flux in airgap B<sub>g</sub> for magnetic materials

(a) Alnico 5

(b) M-5 steel

#### Example: Solution with Alnico PM



NI = 0, so by Ampere's law:

$$H_m l_m + H_g g = 0$$

Solve for H<sub>g</sub>: 
$$H_g = -H_m \left(\frac{l_m}{g}\right)$$

Continuity of flux (Gauss' law):

$$A_{g}B_{g} = A_{m}l_{m} \Longrightarrow B_{g} = B_{m}\left(\frac{A_{m}}{A_{g}}\right)$$

Next, solve for  $B_m$  as a function of  $H_m$ :

$$B_{m} = B_{g} \left( \frac{A_{g}}{A_{m}} \right) = \mu_{o} H_{g} \left( \frac{A_{g}}{A_{m}} \right)$$
$$\implies B_{m} = \mu_{o} \left( -H_{m} \frac{l_{m}}{g} \right) \left( \frac{A_{g}}{A_{m}} \right) = -6.28 \times 10^{-6} H_{m}$$

#### Plot this load line on Alnico BH curve

## Example: Solution with Alnico

• Result:  $B_q = 0.3$  Tesla



Reference: P. Campbell, Permanent Magnet Materials and their Applications, Cambridge University Press, 1994, pp. 89ElectromechanicsMagnetics and Energy Conversion

## Example: Load Line Solution with M-5 Steel

- Use same load line; B<sub>g</sub> = 0.38 Gauss (much lower than with Alnico)
- Note: Earth's magnetic field ~ 0.5 Gauss



# Some Common Permanent Magnet Materials

• Other tradeoffs not shown here include: mechanical strength, temperature effects, etc.



Magnetics and Energy Conversion

# Typical NdFeB B-H Curve

- Neodymium-iron-boron (NdFeB) is the highest strength permanent magnet material in common use today
- Good material for applications with temperature less than approximately 80 - 150C
- Cost per pound has reduced greatly in the past few years
- B/H curve below for "grade 35" or 35 MGOe material



## NdFeB B-H Curves for Different Grades



Reference: Dexter Magnetics, Inc. http://www.dextermag.comElectromechanicsMagnetics and Energy Conversion

# Maximum Energy Product

• BH has units of Joules per unit volume



Why is maximum energy product important?

# Maximum Energy Product



(1)  $B_g = B_m \left( \frac{A_m}{A_n} \right)$  $(2) \ \frac{H_m l_m}{H_g g} = -1$ Let's find B<sub>q</sub><sup>2</sup>  $B_g^2 = \left( B_m \frac{A_m}{A_o} \right) \times \left( \mu_o H_g \right)$  $= -\left(B_m \frac{A_m}{A_o}\right) \left(\mu_o \frac{H_m l_m}{g}\right)$  $=\mu_o\left(\frac{Vol_{mag}}{Vol}\right)\left(-B_mH_m\right)$ 

Solve for magnet volume Volmag

$$Vol_{mag} = B_g^2 \left( \frac{Vol_{gap}}{-B_m H_m} \right)$$

To use minimum volume of magnet for a given  $B_g$ , operate magnet at  $(BH)_{max}$  point

# Progress in PM Specs

• One figure of merit is (BH)<sub>max</sub> product



Reference: J. Evetts, Concise Encyclopedia of Magnetic and Superconducting Materials, Pergamon Press, Oxford, 1992

#### **Progress in PM Specs**



Fig. 7 Development of permanent magnets

a History of  $(BH)_{max}$  values achieved since 1880 b Schematic representation of change in magnet size required for a specific application

Reference: K. Overshott, "Magnetism: it is permanent,"*IEE Proceedings-A*, vol. 138, no. 1, Jan. 1991, pp. 22-31ElectromechanicsMagnetics and Energy Conversion

# **Applications for Permanent Magnets**

- Disk drives
- Speakers
- Motors
  - Rotary motors (Toyota Prius)
  - Linear motors (Maglev, people moving)
- Refrigerator magnets
- Proximity sensors and switches
- Compasses
- Magnetic bearings and magnetic suspensions (Maglev)
- Water filtration
- Plasma fusion research, NMR
- Eddy current brakes (ECBs)
- Etc.

References:

- 1. R. Parker, <u>Advances in Permanent Magnetism</u>, John Wiley, 1990
- 2. P. Campbell, *Permanent Magnet Materials and their Applications*, Cambridge University Press, 1994

#### Example: Maximum Energy Product *Fitzgerald*, Example 1.10: Find magnet dimensions for desired airgap flux density $B_{\alpha} = 0.8$ Tesla



#### **Open-Circuited Permanent Magnet**



Reference: P. Campbell, *Permanent Magnet Materials and their Applications*, Cambridge University Press, 1994, pp. 89

Electromechanics

## **Open Circuited Permanent Magnet --- FEA**


### Short-Circuited Permanent Magnet

• Find B inside core, ignoring any leakage and assuming infinite permeability in core



### **Short Circuited Permanent Magnet**

- For infinite permeability, load line is vertical
- Intersection of load lines occurs at B ≈ B<sub>r</sub>



Reference: P. Campbell, Permanent Magnet Materials and their Applications, Cambridge University Press, 1994, pp. 89

### Short Circuited Permanent Magnet --- FEA



### Circuit Modeling of Permanent Magnets



Reference: E. P. Furlani, Permanent Magnet and Electromechanical Devices, Academic Press, 2001

Electromechanics

### **Circuit Modeling of Permanent Magnets**

LET'S USE THUS IN A MAGNETIC CIRCUIT WITH AIRGAP:



Circuit Modeling of Permanent Magnets  
PUT (3) 
$$TNTO(4)$$
  
 $\binom{B_{m}}{M_{m}} - H_{c} \ell_{m} + H_{g} g = 0$   
 $\frac{1}{4}$   
(3)  $\frac{H_{g}g}{M_{m}} + \frac{B_{m}}{M_{m}} \ell_{m} = H_{c} \ell_{m}$   
 $o_{R} \frac{B_{g}g}{M_{0}} + \frac{B_{m}}{M_{m}} \ell_{m} = H_{c} \ell_{m}$   
 $f_{TOTAL} = K_{L}N_{c} = H_{c} \ell_{m}$   
 $\delta \sigma_{c}$  (5)  $REDUCES TO:$   
 $\frac{1}{2}(R_{g} + R_{m}) = H_{c} \ell_{m}$ 

### **Circuit Modeling of Permanent Magnets**

WE CAN MODEL THIS THE FOLLOWS !



PM MODEL :

# Example: Circuit Modeling of Permanent Magnets

$$\frac{Example}{Grade 37 \text{ NdFeB}}$$
Grade 37 NdFeB
$$H_c = 950,000 \text{ A/m}$$

$$Mm = 1.048 \text{ Mo}$$

$$l_m = 2 \text{ cm}$$

$$g = 1 \text{ cm}$$

$$A_m = Ag = 25 \text{ cm}^2$$
Find Bg

### Example: Circuit Modeling of Permanent Magnets



Solution: H. Lm = (950,000) (0.02) = 19,000  $R_{m} = \frac{l_{m}}{M_{R}A} = \frac{0.02}{(1.048)(417\times10^{-7})(25\times10^{-4})}$ = 6.07×106  $R_g = \frac{g}{M_0} = \frac{0.01}{(4\pi x 10^{-7})(25 \times 10^{-9})}$ = 3.2×10  $\overline{\Phi} = \frac{H_c l_m}{R_a \cdot R_a} = 2.04 \times 10^{-3} W_b$  $B_{g} = \frac{\Phi}{\Delta_{1}} = \frac{2.04 \times 10^{-3}}{25 \times 10^{-4}}$ 0.82 1 0.82 Tes • Bg =

### Example: Circuit Modeling of Permanent Magnets---FEA



## Example: Magnetic Circuit With Steel

- Estimate airgap field B<sub>a</sub> assuming grade 37 NdFeB
- Airgap g, magnet thickness t<sub>m</sub>



### Example: Magnetic Circuit With Steel

• This analysis also ignores leakage



(1) 2 Hm tm + Hg g (Ampere's law) D  $H_{g} = \frac{B_{g}}{M_{0}} = \frac{B_{m}}{M_{0}}$ (constitutive relation) 2Hm tm + 15mg Bm g 2 Hon to Mo 2 tm Mo

Example: Magnetic Circuit With Steel ----Operating Point vs. Magnet Thickness t<sub>m</sub>



$$t_{m} = \frac{g}{2} \longrightarrow B_{g} \sim 0.65T$$

$$t_{m} \simeq g \longrightarrow B_{g} \sim 0.85T$$

$$t_{m} = 2g \longrightarrow B_{g} \sim 1.05T$$

### Example: FEA with Magnet Thickness $t_m = g/2$





### Example: FEA with Magnet Thickness $t_m = g$





### Example: FEA with Magnet Thickness $t_m = 2g$



### Example: Comparison of Different Magnet Thicknesses

	Bpk, 2D analytic	Bpk, 2D FEA
<u>tm</u> = g/2	0.65T	0.58T
tm = g	0.85T	0.73T
tm=2g	1.05T	0.82T



Electromechanics

# PM and a Winding

• Many motors have permanent magnets, steel and windings



Analysis of PM in closed core, with excitation:

$$H_m l_m = NI$$
$$\therefore H_m = \frac{NI}{l_m}$$

## PM and a Winding --- Load Line

 Note that demagnetization can occur if current is sufficiently high



### Another Example --- Excitation and Airgap



(1) Ampere's law:  $H_m l_m + H_g g = NI$ 

(2) Constitutive law:  $B_g = \mu_o H_g$ 

(3) Gauss' law: 
$$B_m A_m = B_g A_g$$

Solve for B<sub>m</sub>-H<sub>m</sub> load line:

$$B_m = -\mu_o \left(\frac{A_m l_m}{A_m g}\right) \left(H_m - \frac{NI}{l_m}\right)$$

### Another Example --- Excitation and Airgap ---Load Line



### **Interesting Calculation Tool**

	Home   Conta	oct Email Total Magnetic Solutions™	
Products   Magnet Desi	gn   Info Request	PDF Catalogs	
Length Width Thickness Distance X Ceramic 1 Gauss at X Ca	25.4 12.7 5.08 0.100 2,200 527	Calc Der Recta Use to c density the surfa center-li shaped Enter the Thicknes distance select th pull dow the Calc result. D	culate the Flux isity of a Plain angular Magnet alculate the flux at a distance X above ace and on the ne of a rectangular magnet. A Length, Width, and so of the magnet, X from the surface, the material from the n menu, and press ulate button for the distance units can be

2-130

Reference: www.magnetsales.com

### **NdFeB Rounds**

What Can	You
Buy?	

Part Number	Material	Diameter	Length	Orientation
PN35C1250B-N	N36	0.123	0.250	L
PN45C0140B	N45	0.140	0.500	D
PN45C0189B	N45	0.188	0.057	L
94C5668B	94EB	0.250	0.100	L
CM40685	4014	0.250	0.125	L
PN36C0250B	N36	0.250	0.250	L
97C5513B	97CB	0.250	2.000	L
97C5613B	97CB	0.251	0.200	L
PN45C1200B	N45	0.328	1.200	D
PN36SHC0330B	N36SH	0.330	0.330	L
94C5536C	94EB	0.370	0.250	L
97C5446C	97CB	0.375	0.125	L
94C5562B	94EB	0.375	2.100	L
94C4822B	94EA	0.499	0.188	L
NA67A460	34B	0.500	0.190	L
CM41085-2630	2630	0.500	0.250	L
CM41086-3220	3520	0.500	0.250	L
CM40713-3714	4014	0.500	0.250	L
CM41087-3714	4014	0.625	0.250	L
CM41088-2630	2630	0.625	0.250	L
CM40884-3714	4014	0.866	0.393	L
CM41089-3714	4014	0.875	0.500	L
CM41090-2630	2630	0.875	0.500	L
CM41091-2630	2630	1.000	0.500	L
CM41092-3220	3520	1.000	0.500	L
CM41093-3714	4014	1.000	0.500	L



. \_\_\_\_\_\_ \_\_\_\_\_\_\_\_\_\_

Reference: www.dextermag.com Electromechanics

### **NdFeB Blocks**





# What Can You Buy?

Part Number	Material	Thickness	Width	Length	Orientation
CM41030-3714	4014	0.250	0.325	0.500	T
CM41094-2630	2630	0.250	0.500	0.500	T
CM41095-3220	3520	0.250	0.500	0.500	T
CM41096-3714	4014	0.250	0.500	0.500	T
PN36HR2933B	N36H	0.293	0.560	1.044	T
PN38HR0990B	N38H	0.315	0.750	0.990	T
PN38HR0375B	N38H	0.375	0.866	2.362	T
CM40325-3714	4014	0.500	0.750	0.750	T
CM40729-3714	4014	0.500	1.000	1.000	T
CM41097-2630	2630	0.500	1.000	1.000	T
CM41098-3220	3520	0.500	1.000	1.000	T
CM40975-3714	4014	0.590	0.750	0.750	T
PN38HR0122B	N38H	1.000	2.000	2.000	T
CM41099-2630	2630	1.000	2.000	2.000	T
CM40680-3714	4014	1.000	2.000	2.000	T
PN48R0100B	N48	1.000	2.000	2.000	T

Rectangular Magnets - Finished Sizes sorted in ascending order of Length, Width, and then Thickness.

Thickness.					
Item Number	Grade	L	w	т*	Condition
35NE111111	35	0.175	0.175	0.175	Die Pressed, Machined
35NE111111- NI	35	0.175	0.175	0.175	Die Pressed, Machined, Nickel Plated
30NE261916- NI	30	0.400	0.290	0.250	Die Pressed, Machined, Nickel Plated
35NE301412	35	0.475	0.230	0.190	Die Pressed, Machined
35NE323232- NI	35	0.500	0.500	0.500	Die Pressed, Machined, Nickel Plated
35NE501212	35	0.790	0.195	0.195	Die Pressed, Machined
35NE642424	35	1.000	0.375	0.375	Die Pressed, Machined
35NE646416	35	1.000	1.000	0.250	Die Pressed, Machined
35NE646432	35	1.000	1.000	0.500	Die Pressed, Machined
35NE646432- NI	35	1.000	1.000	0.500	Die Pressed, Machined, Nickel Plated
35NE209620	35	1.500	0.305	0.305	Die Pressed, Machined
35NE281107	35	2.000	0.170	0.107	Die Pressed, Machined
35NE2812832	35	2.000	2.000	0.500	Die Pressed, Machined
35NE2812832	35	2.000	2.000	0.500	Die Pressed, Machined
35NE2812864	35	2.000	2.000	1.000	Die Pressed, Machined
Tolerances on "machined" blocks are the greater of $\pm 1.5\%$ of the dimension or $\pm 0.015$ " on cross sectional					

dimensions, and  $\pm 0.005$ " on the orientation direction.

Reference: www.magnetsales.com

What Can You

Buy?

Electromechanics

Magnetics and Energy Conversion

The T\* dimension represents the

orientation direction.

### **Magnetization Patterns**



#### Different Magnetizing Patterns Give Different Results

#### Except for the regular Flexible and Ceramic 1 materials, all magnet materials are "pre-oriented" and can only be magnetized in a particular direction.

Standard (or "conventional") magnetization is straight through the orientation direction, and produces one North pole and one South pole. The Rare Earth magnets are extremely difficult to magnetize in non-standard ways. However, the Flexible and Ceramic types can be magnetized in many non-standard ways to give special results.

Reference: www.magnetsales.com

### Comparison







Reference: www.magnetsales.com

Electromechanics

### Comparison of Maximum Operating Temperatures



Reference: http://www.electronenergy.com/media/Magnetics%202005.pdf

Electromechanics

### Comparison of Maximum Operating Temperatures



### Magnet Comparisons

Material	Approx. Maximum Operating Temperatures		
	°C	٥F	
NdFeB	140	284	
SmCo	300	572	
Ferrite	300	572	
Alnico	540	1,004	
Flexible	100	212	

Material	BHmax	Relative Cost (\$ / pound)	Relative Cost (\$ / BHmax)
Flexibible	1	\$1,00	\$0.60
Ceramic	3	\$2,00	\$0.50
Alnico	5	\$20.00	\$4.30
SmCo	20	\$100.00	\$6.00
NdFeB	40	\$50.00	\$1.40

Reference: www.magnetsales.com

Electromechanics

### **PM Online Resources**

- <u>http://members.aol.com/marctt/</u>
- www.dextermag.com
- <u>www.magnetsales.com</u>
- http://www.grouparnold.com/
- Magnetic Materials Producers Association (MMPA standard)

# Some Very Brief Comments on Superconductors

- Superconductors have zero resistance if the temperature is low enough, the field acting on the superconductor is low enough, and the current through the superconductor is low enough
- Superconductors are classified as "low temperature" (NbTi, NbSn) or "high temperature" (YBCO, BSCCO)
- Low-Tc superconductors are usually chilled with liquid helium (4.2K)
- High-Tc superconductors are usually used in the 20K-77K range

Reference: Y. Iwasa "Case Studies in Superconducting Magnets," Plenum Press, 1994

### Some Data on Low-Tc Material

- Shown for niobium titanium
- This type of superconductor is used in the Japanese MLX 500 km/hr Maglev



### Some Data on High-Tc Material

Some superconductors are anisotropic; i.e. superconducting tapes





Reference: American Superconductor, www.amsuper.com

### Quotes

It is well to observe the force and virtue and consequence of discoveries, and these are to be seen nowhere more conspicuously than in printing, gunpowder, and the magnet. --- Sir Francis Bacon

The mystery of magnetism, explain that to me! No greater mystery, except love and hate. ---John Wolfgang von Goethe

### Transformers --- Overview

- Selected history
- Types of transformers
- Voltages and currents
- Equivalent circuits
- Voltage and current transformers
- Per-unit system
#### **Selected History**

- 1831 --- Transformer action demonstrated by Michael Faraday
- 1880s: modern transformer invented



Photo of Faraday's original transformer (courtesy MIT Burndy Library).

Reference: J. W. Coltman, "The Transformer (historical overview)," *IEEE Industry Applications Magazine*, vol. 8, no. 1, Jan.-Feb. 2002, pp. 8-15



Magnetics and Energy Conversion



This Stanley transformer from the first ac power station in Great Barrington, Massachusetts, dates from 1885. The transformer is about a foot long; copper windings wrapped with cotton protrude between wood endpieces at the left. The middle arm of E-shaped iron laminations was slid into the prewound coil in alternating directions. The ends of the other two arms are visible as dense regions at the top and bottom of the laminations.

## Early Transformer (Stanley, c. 1880)

(No Model.)

No. 349,611.

W. STANLEY, Jr. INDUCTION COIL. Patented Sept. 21, 1886.





William Stanley



# Faraday's Law

• A changing magnetic flux impinging on a conductor creates an electric field and hence a current (eddy current)

$$\oint_C E \cdot dl = -\frac{d}{dt} \int_S B \cdot dA$$

- The electric field integrated around a closed contour equals the net time-varying magnetic flux density flowing through the surface bound by the contour
- In a conductor, this electric field create  $\frac{1}{\sqrt{2}}$ a current by:  $J = \sigma E$



• Induction motors, brakes, etc. Electromechanics Magnetics and Energy Conversion

#### Magnetic Circuit with Two Windings

• Note that flux is the sum of flux due to  $i_1$  and that due to  $i_2$ 



# **Types of Transformers**

• There are many different types and power ratings of transformers: single phase and multi-phase, signal transformers, current transformers, etc.

## Instrument Transformer

- Instrument transformers (voltage and current) provide line current and line voltage information to protective relays and control systems
- Current transformer shown below



Reference: L. Faulkenberry and W. Coffer, *Electrical Power Distribution and Transmission*, Prentice Hall, 1996, pp. 131

Electromechanics

# 200A Current Transformer (CT)





#### Applications

- Sensing Overload Current
- Ground fault detection
- Metering
- Analog to Digital Circuits

#### Electrical Specifications @ 20°C ambient

Electrical Specifications		
Primary Current		200A nom., 500A max.
Turns Ratio		1000:1 nominal
lo%idlt per Amp Ratio at 200A for 100 ohm		0.100 V/A
Volt per Amp Ratio at 20A for 100 ohm load		0.0991 V/A
DC Resistance at 20°C		11 ohms
Dielectric Withstanding Voltage (Hi-pot)		4KVrms
Mechanical Specifications		
Case	Polycarbonate	
Encapsulant	Ероху	
Flammibility	Conforms to UL94-VO	
Terminals	Pins Ø 1.0mm	
Marking	TALEMA Date Code (W/Y) AC1200, Dot at start pin	
Approximate Weight	150 grams	
Tolerance	±0.2mm	

Reference: http://rocky.digikey.com/WebLib/Amveco-Talema/Web%20Data/AC1200.pdf

Electromechanics

# Voltage Instrument Transformer



#### Voltage Transformers

#### Applications

For single phase voltage measurement in AC power system

#### Features

- Resin cast moulded plastic cases
- Integral fuses available on some models
- Designed to meet IEEE C57.13
- 50Hz design available
- UL Recognized and CSA Approved

Reference: http://www.geindustrial.com/products/brochures/ITI.pdf

#### Audio Transformer

#### P.C. BOARD MOUNT - EPOXY POTTED BROADCAST QUALITY AUDIO TRANSFORMERS

- Rugged black epoxy potted case with 9 pin connections (.025" square by 0.5" long).
- Frequency response @ 0 dbm +/- 1 db max. (+/- 0.5 db is typical) of 30 Hz. to 30 Khz., except 560Q which is 30 Hz. to 15 Khz.





Reference: http://rocky.digikey.com/WebLib/Hammond/Web%20Data/560,%20800-844,%20850%20Series.pdfElectromechanicsMagnetics and Energy Conversion

#### Pulse Transformer

• Used for triggering SCRs, etc. where isolation is needed



- A. Electrical specifications (@ 25 ° C)
  - Leakage Inductance; 20 μ H MAX
  - DC Resistance; Primary (1-2) 2.5 Ω MAX Secondary (3-4) 1.5 Ω MAX
  - Primary ÉT-constant; 90.0V- μs MIN
  - 4. Turns Ratio;
  - (1-2) : (3-4) = 2 : 1.00 ±5%
  - Interwinding Capacitance; 80.0 pF MAX
  - Primary Inductance;
     1.0 mH MIN
  - Dielectric Strength; AC 2600 Vrms 1 minute @ Pri to Sec

Reference: http://rocky.digikey.com/WebLib/Tamura-Microtran/Web%20Data/STT-107.pdf

Electromechanics

# Power Distribution Transformer

- Provides voltage for the customer
- Typical voltages are 2.3-34.5kV primary, and 480Y/277V or 208Y/120V 3-phase or 240/120V single phase
- Pole-top transformers typically 15-100 kVA





Reference: http://www.geindustrial.com/products/brochures/DEA-271-English.pdf

Electromechanics

#### E Core Transformer



**Figure 30-6** Dimensioned diagram of (a) a double-E core (b) bobbin, and (c) assembled core with winding.

#### **Offline Flyback Power Supply**



P. Maige, "A universal power supply integrated circuit for TV and monitor applications," *IEEE Transactions on Consumer Electronics*, vol. 36, no. 1, Feb. 1990, pp. 10-17

Electromechanics

#### **Transcutaneous Energy Transmission**



Fig. 1. Transcutaneous energy transmission system for an implantable artificial heart.



Fig. 2. Transcutaneous transformer.

H. Matsuki, Y. Yamakata, N. Chubachi, S.-I. Nitta and H. Hashimoto, "Transcutaneous DC-DC converter for totally implantable artificial heart using synchronous rectifier," *IEEE Transactions on Magnetics*, vol. 32, no. 5, Sept. 1996, pp. 5118 - 5120

Electromechanics

#### **Power Transformer**



The typical modern transformer is submerged in oil for insulation and cooling and is sealed in an airtighttank. Low- and high-voltage power lines lead to and from the coils through ceramic bushings. Inside the transformer, coils and core are packed close together to minimize electrical losses and material costs. The oil coolant circulates by convection through external radiators. In large transformers cooling is expedited by attaching fans to the radiators and circulation the oil with pumps.

Reference: J. W. Coltman, "The Transformer (historical overview)," *IEEE Industry Applications Magazine*, vol. 8, no. 1, Jan.-Feb. 2002, pp. 8-15

Electromechanics

## Superconducting Transformer



Fig. 13. Schematic of the major system components of a 5/10MVA HTS transformer.



Fig. 15. Completed 5/10 MVA WES/SP/ORNL HTS transformer under test at the Waukesha Electric test facility.

Reference: W. Hassenzahl et. al., "Electric Power Applications of Superconductivity," Proceedings of the IEEE, vol. 92, no. 10, October 2004, pp. 1655-1674 Electromechanics



If resistive drop in winding is negligible:

$$\Phi_{\rm max} = \frac{E_{1,\rm rms}}{\sqrt{2}\pi fN}$$

# No-Load Phasor Diagram



- Winding current has harmonics, and fundamental is generally out of phase with respect to flux
- In-phase component is from core losses

$$P_c = E_1 I_{\varphi} \cos \theta_c$$

• Magnetizing current is 90 degrees out of phase

#### **Example: Transformer Calculations**

• <u>Fitzgerald</u>, Example 2.1. In Example 1.8, the core loss and VA at Bmax = 1.5T and 60 Hz were found to be:  $P_c =$ 16W and VI = 20 VA with induced voltage 194V. Find power factor, core loss current I<sub>c</sub> and magnetizing current I<sub>m</sub>.



Example 1.8.

Electromechanics

Magnetics and Energy Conversion

 $\hat{I}_{\rm m}$ 

 $\hat{\Phi}$ 

 $\hat{I}_{c}$ 

 $\hat{E}_1$ 

Example: Transformer Calculations --- Solution Power factor:

$$PF = \cos(\theta_c) = \frac{16}{20} = 0.8$$

#### Exciting current

$$I_{\varphi} = \frac{VA}{V} = \frac{20}{194} = 0.1A$$

# Core loss component $I_c = \frac{16}{194} = 0.082A$

Magnetizing component  $I_m = I_{\varphi} |\sin \theta_c| = 0.060 A$ 

Electromechanics







Ideal Transformer with Load

By Ampere's law:

$$N_1 i_1 - N_2 i_2 = 0 \Longrightarrow \frac{i_1}{i_2} = \frac{N_2}{N_1}$$

(Also, by power balance,  $v_1 i_1 = v_2 i_2$ )

#### **Impedance Transformation**



Therefore, impedance at input terminals is:

$$\frac{\hat{V_1}}{\hat{I}_1} = Z_2 \left(\frac{N_1}{N_2}\right)^2$$

Electromechanics

## **Equivalent Circuits**

• These 3 circuits have the same impedance as seen from the a-b terminals





# Example: Use of Equivalent Circuits

- *Fitzgerald*, Example 2.2
- (a) Draw equivalent circuit with series impedance referred to primary
- (b) For a primary voltage of 120VAC and a short at the output, find the primary current and the short circuit current at the output



#### **Example: Impedance Transformation**

$$R_{2}' + jX_{2}' = \left(\frac{N_{1}}{N_{2}}\right)^{2} \left(R_{2} + jX_{2}\right)$$
$$= 25 + i100$$



#### Example: Input Current with Output Short Circuit



$$I_{1} = 0.28 - j(1.13)$$

$$I_{1,rms} = \sqrt{0.28^{2} + 1.13^{2}} = 1.16A$$

$$\hat{I}_{2} = 5\hat{I}_{1} = 1.4 - j(5.65)$$

$$I_{2,rms} = \sqrt{1.4^{2} + 5.65^{2}} = 5.8A$$

Electromechanics

# Non-Ideal Effects in Transformers --- Magnetizing Inductance

• A real-world transformer doesn't pass DC

5

- From either set of terminals, the impedance looks like an inductor if the other set of terminals is open-circuited
- Can model this as an ideal transformer with a <u>magnetizing</u> <u>inductance</u> added.
- The magnetizing current i<sub>m</sub> produces the mutual flux which couples to the secondary



#### Mutual and Leakage Flux

• Not all of the flux created by winding #1 links with winding #2.

MUTUAL FLUX



#### Mutual and Leakage Flux



# Non-Ideal Effects in Transformers --- Leakage

- Not all of the flux created by winding #1 links with winding #2.
- Therefore, real-world voltage transformation is not exactly equal to the turns ratio, due to the voltage drops on L<sub>k1</sub> and L<sub>k2</sub>



#### **Transformer Equivalent Circuits**







Magnetics and Energy Conversion

# Example: Use of Equivalent Circuits

• Fitzgerald, Example 2.3: A 50-kVA 2400:240V 60 Hz distribution transformer has a leakage impedance of 0.72+j0.92 $\Omega$  in the high voltage winding and 0.0070 + j0.0090  $\Omega$  in the low-voltage winding. The impedance  $Z\phi$  of the shunt branch (equal to  $R_c$  +j $X_m$  in parallel) is 6.32 + j43.7  $\Omega$  when viewed from the low voltage side.

Draw the equivalent circuits referred to the high voltage side and the low voltage sides.

SOLUTION: Note that N1:N2 is 1:10, so impedances step up and down by 100

#### **Example:** Solution

--- Leakage impedance of 0.72+j0.92 $\Omega$  in the high voltage winding and 0.0070 + j0.0090  $\Omega$  in the low-voltage winding. --- The impedance  $Z\phi$  of the shunt branch (equal to R<sub>c</sub> +jX<sub>m</sub> in parallel) is 6.32 + j43.7  $\Omega$  when viewed from the low voltage side.



# Approximate Transformer Equivalent Circuits

- "Cantilever circuits"
- Ignoring voltage drop in primary or secondary leakage impedances



# Approximate Transformer Equivalent Circuits

Circuit if we ignore the magnetizing inductance and core resistance



• Circuit if we further ignore the winding resistance



#### Example: Use of Cantilever Circuit

• *Fitzgerald*, Example 2.4



Electromechanics
# Example: Find V<sub>2</sub>

• *Fitzgerald*, Example 2.5





Magnetics and Energy Conversion



From node equations:  $\hat{V}_s = \hat{V}_2 + \hat{I}_L R + j X \hat{I}_L$ 



Magnetics and Energy Conversion



-We need length of vector Oa (which is V<sub>2</sub>) -We know length of vector Oc (which is 2400V)  $ab = IR \cos \theta + IX \sin \theta = (20.8)(1.72)(0.8) + (20.8)(3.42)(0.6) = 71.4$   $bc = IX \cos \theta - IR \sin \theta = 35.5$ Solve for V<sub>2</sub>:  $(V_2 + ab)^2 + (bc)^2 = V_s^2 \Rightarrow V_2 = 233V$ 

Electromechanics

# Transformer Testing to Determine Parameters

- By doing various tests on a transformer, we can determine the equivalent circuit parameters
- Testing includes open-circuit and short-circuit testing

#### Short-Circuit Test



#### **Short-Circuit Testing**



# Normally: $L_m >> L_{k1}$ , $L_{k2}$ and $R_c >> R_{w1}$ , $R_{w2}$



Using the simplified circuit, we can approximate:

$$\begin{aligned} \left| Z_{eq} \right| &\approx \frac{V_{TEST}}{I_{TEST}} \\ R_{SC} &= R_{W1} + R_{W2}^{'} = \frac{P_{SC}}{I_{TEST}^{2}} \\ X_{SC} &\approx \sqrt{\left| Z_{eq} \right|^{2} - R_{SC}^{2}} \end{aligned}$$

#### **Open-Circuit Testing**



(a)



Magnetics and Energy Conversion

# **Open-Circuit Testing**

• There is no secondary current



#### Autotransformer

#### **Conventional transformer**

 $\mathbb{S}^{N_2}$ 

Autotransformer redrawn



#### **Connection as autotransformer**



#### Staco Autotransformer



Reference: Staco

Electromechanics

#### Autotransformer Drawing



Electromechanics

#### Autotransformer Brush



#### Damaged Autotransformer



# Example: Autotransformer

- *Fitzgerald*, Example 2.7
- 2400:240V 50-kVA transformer is connected as an autotransformer with ab being the 240V winding and bc is the 2400V winding.
- (a) Compute the kVA rating
- (b) Find currents at rated power



Magnetics and Energy Conversion

## Example: Autotransformer Example --- Solution

For 50 kVA, rating of 240V winding is: 50000/240 = 208A

The autotransformer VA rating is:  $V_H I_H = (2.64kV)(208A) = 549 kVA$ 

Rated current at low-voltage winding:

$$I_L = I_H \left(\frac{2640}{2400}\right) = 229A$$



# Some Comments on Autotransformers

- Autotransformers differ from isolation transformers in that there is no isolation between primary and secondary
- However, this lack of isolation allows some of the transferred power to be conducted from primary to secondary instead of magnetic induction
- Autotransformers in general require less core material per kVA rating
- Autotransformers used where lack of isolation doesn't pose a safety issue

# Example: Magnetic Circuit Problem

- *Fitzgerald*, Problem 2.2
- A magnetic circuit with a cross-sectional area of 15 cm<sup>2</sup> is to be operated from a 120V RMS supply. Calculate the number of turns required to achieve a peak magnetic flux density of 1.8 Tesla in the core



Example:

# Magnetic Circuit Problem --- Solution

Flux is:  $\Phi = \Phi_{max} \sin(\omega t)$ 

The time rate of change of flux is:  $\frac{d\Phi}{dt} = \omega \Phi_{\text{max}} \cos(\omega t)$ 

The time rate of change of flux linkage is:  $\frac{d\lambda}{dt} = N \frac{d\Phi}{dt} = N \omega \Phi_{\text{max}} \cos(\omega t) = V$ 

Let's relate flux density to flux:  $\frac{\Phi_{\text{max}}}{A} = B_{\text{max}}$ 

So, we can solve for N

$$N = \frac{\sqrt{2}V}{\omega B_{\text{max}}A} = \frac{(\sqrt{2})(120)}{(2\pi \times 60)(1.8)(1.5 \times 10^{-3})} = 166.7$$

Round up to N = 167

# Example: Transformer Problem

- *Fitzgerald*, Problem 2.4
- A 100-Ohm resistor is connected to the secondary of an ideal transformer with a turns ratio of 1:4 (primary to secondary). A 10V RMS, 1-kHz voltage source is connected to the primary. Calculate the primary current and the voltage across the 100-Ohm resistor



#### Example: Transformer Problem --- Solution

$$I = \frac{1}{2}$$

We know that this is a step-up transformer, so  $V_1 = 10V$  and  $V_2 = 40V$ .

We next find the secondary current I2

$$I_2 = \frac{40V}{100\Omega} = 0.4A$$

The voltage steps up, so the current steps down; hence

 $I_1 = 4I_2 = 1.6A$ 

Electromechanics

#### **3-Phase Connections of Transformers**



# Example: Finding 3-Phase Currents

 Problem: A three phase, 208V (line-line) Y connected load has:

$$- Z_{an} = 3 + j4$$
  
 $- Z_{bn} = 5$   
 $- Z_{cn} = -5j$ 

- Find
  - (a) Phase voltages
  - (b) Line and phase currents
  - (c) Neutral currents

#### Example: Finding 3-Phase Currents --- Solution



Line-neutral voltages are found by taking the lineline voltage and dividing by  $\sqrt{3}$ 

$$V_{L-N} = \frac{208}{\sqrt{3}} = 120$$

#### Example: 3-Phase Currents --- Solution



Line (also called phase) currents are found by taking the line-line voltages and dividing by impedance

$$I_{a} = \frac{120\angle 0^{\circ}}{(3+4j)} = 24\angle -53.13^{\circ}$$
$$I_{b} = \frac{120\angle 120^{\circ}}{(5)} = 24\angle 120^{\circ}$$
$$I_{c} = \frac{120\angle 240^{\circ}}{(-5j)} = 24\angle -30^{\circ}$$

Electromechanics

# Example: 3-Phase Currents --- Solution

 Note that loads are unbalanced so there is a net neutral current

$$I_n = I_a + I_b + I_c = 25.4 \angle 155.9^{\circ}$$

## 480V Y System

• Line-line = 480V; line-neutral = 277V



FIGURE 1-1 480Y/277-Volt System

Reference: Ralph Fehr, Industrial Power Distribution, Prentice Hall, 2002

Electromechanics

# Delta System

• Line-line = 480V



FIGURE 1-2 High-Leg Delta System

Reference: Ralph Fehr, *Industrial Power Distribution*, Prentice Hall, 2002

Electromechanics

# Instrument Transformer

 Used for protection, relaying, voltage or current monitoring, etc.



# Per-Unit System

- Computations in electric machines and transformers are often done using the "per-unit" system
- Actual circuit quantities (Watts, VArs, etc.) are scaled to the per-unit system
- This method allows removal of transformers from diagrams
- To convert to per-unit, 4 base quantities are established
  - Base power VA<sub>base</sub>
  - Base voltage  $V_{\text{base}}$
  - Base current I<sub>base</sub>
  - Base impedance  $Z_{\text{base}}$

# Example: Per-Unit System

- Example: A system has  $Z_{base} = 10 \ \Omega$  and  $V_{base} = 400V$ . Find base VA and  $I_{base}$
- Solution:

$$-I_{base} = V_{base}/Z_{base} = 400/10 = 40A$$
$$- (VA)_{base} = V_{base}I_{base} = (400)(40) = 16 \text{ kVA}$$

# Example: Per-Unit System

- A 5 kVA, 400/200V transformer has 2  $\Omega$  reactance referred to the 200V side. Express the transformer reactance in p.u.
- Solution:

- 
$$(VA)_{base} = 5000$$
  
-  $V_{base} = 200$   
-  $I_{base} = (VA)_{base}/V_{base} = 5000/200 = 25A$   
-  $Z_{base} = V_{base}/I_{base} = 200/25 = 8 \Omega$   
-  $Z = 2.0/8.0 = 0.25 \text{ p.u.}$ 

# Example: Per-Unit Applied to Transformer

- *Fitzgerald*, Example 2.12
- Convert this circuit showing a 100 MVA transformer to the per-unit system







In per-unit system:  $R_{H} = \frac{0.085}{63.5} = 0.00133 \ p.u.$  $X_{H} = \frac{3.75}{63.5} = 0.059 \ p.u..$ 

Electromechanics

#### Example: Model

• Turns ratio is 1:1, so we can remove transformer



#### Example: Get Rid of 1:1 Transformer


# Energy Conversion --- Overview

- Forces and torques
- Energy balance
- Determining magnetic forces and torques from energy
- Multiply-excited systems
- Forces and torques in systems with permanent magnets

#### **Right-Hand Rule**

• For determining the direction magnetic-field component of the Lorentz force  $F=q(v \times B) = JxB$ .



## Example: Single-Coil Rotor

- *Fitzgerald*, Example 3.1
- Find  $\theta\text{-directed}$  torque as a function of  $\alpha$



Electromechanics

### **Example: Single-Coil Rotor**



For wire #1:  $F_{1\theta} = -IlB_{\rho} \sin \alpha$ 

For wire #2:  $F_{2\theta} = -IlB_o \sin \alpha$ 

Total torque (T = force × distance):  $T_{\theta} = -2IlB_o \sin \alpha R$ 

What happens if B points left-right instead of up-down?  $T_{\theta} = -2IlB_{o} \cos \alpha R$ 

# Electromechanical Energy Conversion Device

- This box can be used to model motors, actuators, lift magnets, etc.
- Note 2 electrical terminals (voltage and current) and 2 mechanical terminals (force  $f_{fld}$  and position x)
- The lossless magnetic energy storage system converts electrical energy to mechanical energy



# Interaction Between Electrical and Mechanical Terminals

 $W_{FLD}$  = stored magnetic energy In words, the rate of change of magnetic energy equals the power in minus the mechanical work out

$$\frac{dW_{FLD}}{dt} = ei - f_{fld} \frac{dx}{dt}$$

By Faraday's law,  $e = d\lambda/dt$ , so let's rework:

$$\frac{dW_{FLD}}{dt} = i\frac{d\lambda}{dt} - f_{fld}\frac{dx}{dt}$$

Multiply through everywhere by dt:

$$dW_{FLD} = id\lambda - f_{fld}dx$$

Electromechanics

# Interaction Between Electrical and Mechanical Terminals

In a lossless system, we can rewrite the energy balance:

 $dW_{\rm ELEC} = dW_{\rm MECH} + dW_{\rm FLD}$ 

Differential energy in:  $dW_{ELEC} = id\lambda$ Differential work out:  $dW_{MECH} = f_{fld} dx$ Change in magnetic energy:  $dW_{FLD}$ 

### **Force-Producing Device**

• This solenoid is an example of a force-producing device



# Energy

Thinking about energy, we start out with:  $dW_{FLD} = id\lambda - f_{fld}dx$ 

If magnetic energy storage is lossless, this is a conservative system and  $W_{fld}$  is determined by state variables  $\lambda$  and x

In a conservative system, the path you take to do this integration doesn't matter

#### Another Conservative System

• Roller coaster, ignoring friction, the path doesn't matter. Speed of both coasters is the same at the bottom of the hill



HILL #1

HILL #2

#### Magnetic Relay

• This illustrates lossless magnetic structure with external losses due to resistance



# Integration Path for Finding Magnetic Stored



$$W_{FLD}(\lambda_o, x_o) = \int_{path2a} dW_{FLD} + \int_{path2b} dW_{FLD}$$

On path 2a,  $d\lambda = 0$  and  $f_{fld} = 0$  since zero  $\lambda$  means zero magnetic force, therefore:

$$\sum_{x} W_{FLD}(\lambda_o, x_o) = \int_0^\lambda i(\lambda, x_o) d\lambda$$

#### Special Case --- Linear System



# Example: Relay with Movable Plunger

- *Fitzgerald*, Example 3.2
- $\bullet$  Find magnetic stored energy  $W_{\text{FLD}}$  as a function of x with
- I = 10A



#### Example: Relay with Movable Plunger



 $W_{FLD} = \frac{1}{2} \frac{\lambda^2}{L(x)} \text{ with I constant.}$   $W_{FLD} = \frac{1}{2} \frac{L^2(x)I}{L(x)} + \frac{1}{2} \frac{L^2(x)I}{L(x)} + \frac{1}{2} \frac{L^2(x)I^2}{L(x)} = \frac{1}{2} L(x)I^2$ (b)  $W_{FLD} = \frac{1}{2} \frac{L^2(x)I^2}{L(x)} = \frac{1}{2} L(x)I^2$ 

I'll give you that  $L(x) = \frac{\mu_o N^2}{2g} ld(1 - \frac{x}{d})$ ,

so magnetic stored energy is:

$$W_{FLD} = \frac{\mu_o N^2}{4g} ld(1 - \frac{x}{d})I^2$$

Electromechanics

### **Determining Magnetic Force from Stored Energy**

• Next, if we go to all this trouble to find stored energy, let's figure out how to find forces from the energy (very important!) Remember  $dW_{FLD} = id\lambda - f_{fld}dx$ 

Next, remember the "total differential" from calculus:

$$dF(x_1, x_2) = \frac{\partial F}{\partial x_1} \bigg|_{x_2 = const.} dx_1 + \frac{\partial F}{\partial x_2} \bigg|_{x_1 = const.} dx_2$$

Let's rewrite the stored energy expression:

$$dW_{FLD} = \frac{\partial W_{FLD}}{d\lambda} \bigg|_{x} d\lambda + \frac{\partial W_{FLD}}{dx} \bigg|_{x}$$

From this, we see that

$$i = \frac{\partial W_{FLD}}{\partial \lambda} \Big|_{x}$$
 and  $f_{fld} = -\frac{\partial W_{FLD}}{\partial x} \Big|_{\lambda}$ 

#### **Determining Magnetic Force from Energy**

For linear systems with  $\lambda = L(x)I$ 

Energy 
$$W_{FLD} = \frac{1}{2} \frac{\lambda^2}{L(x)}$$

Force:  

$$\begin{aligned}
f_{fld} &= -\frac{\partial}{\partial x} \left( \frac{1}{2} \frac{\lambda^2}{L(x)} \right) \\
&= \frac{\lambda^2}{2L^2(x)} \frac{dL(x)}{dx}
\end{aligned}$$

With 
$$\lambda = L(\mathbf{x})I$$
  
 $f_{fld} = \frac{I^2}{2} \frac{dL(x)}{dx}$ 

Electromechanics

# **Determining Magnetic Force from Energy**

• The bottom line: <u>if</u> your system is linear, and <u>if</u> you can calculate inductance as a function of position, then finding the force is pretty easy

# Example: Curve Fit for Inductance of Solenoid with Plunger

- *Fitzgerald*, Example 3.3
- Assume that the following inductance vs. plunger position was measured. We then run the solenoid with 0.75A current



Electromechanics

# Example: Force as a Function of Position

• We can fit a polynomial to the inductance, and use energy methods to find the plunger force as a function of position



Electromechanics

# **Torque in Magnetic Circuit**

• Can solve this as before, by analogy Rotor axis +λ  $\rightarrow$  Stator axis Rotor Air gap Stator By analogy:  $T_{fld} = \frac{I^2}{2} \frac{dL(\theta)}{d\theta}$ 

# Example: Finding Torque

#### • *Fitzgerald*, Example 3.4



Assume  $L(\theta) = L_0 + L_2 cos(2\theta)$  with  $L_0 = 10.6$  mH and  $L_2 = 2.7$  mH. Find the torque with I = 2A.

Solution:

$$T(\theta) = \frac{I^2}{2} \frac{dL(\theta)}{d\theta} = +\frac{I^2}{2} \left(-2L_2 \sin(2\theta)\right)$$
$$= -1.08 \times 10^{-2} \sin(2\theta) N - m$$

# Example: Finding Torque

#### • *Fitzgerald*, Practice Problem 3.4



Assume  $L(\theta) = L_0 + L_2 cos(2\theta) + L_4 sin(4\theta)$  with  $L_0 = 25.4$  mH,  $L_2 = 8.3$  mH and  $L_4 = 1.8$  mH. Find the torque with I = 3.5A.

Solution:  $T(\theta) = -0.1017 \sin(2\theta) + 0.044 \cos(4\theta) N - m$ 

Electromechanics

#### Another Example --- Torque vs. Rotor Angle



# Today's Summary

- Today we've covered:
  - Maxwell's equations: Ampere's, Faraday's and Gauss' laws
  - Soft magnetic materials (steels, etc.)
  - Hard magnetic materials (permanent magnets)
  - Basic transformers
  - The per-unit system
  - We started electromechanical conversion basics